



SOUTH TOWER - MECHANICS OF TILTING TOP



BLOCK MISCONCEPTION A


REQUIRES EAST ROW OF FACADE COLUMNS TO SUPPORT ENTIRE 32 FLOORS OF TILTING TOP



BLOCK MISCONCEPTION B


REQUIRES EAST ROW OF FACADE COLUMNS TO SUPPORT ENTIRE 32 FLOORS OF TILTING TOP AND BE CRUSHED PROGRESSIVELY

BLOCK MISCONCEPTION A & B DO NOT MATCH OBSERVATIONS OF DOWNWARD PROGRESSION OF MASS EJECTIONS



CRUSH UP - CRUSH DOWN

CRUSH UP-CRUSH DOWN MATCHES OBSERVATIONS OF DOWNWARD PROGRESSION OF MASS EJECTIONS



PRELIMINARY